



## ORDER TO CONTROL LEAD HAZARDS

*This order is issued under section 3742.37 of the Ohio Revised Code and rule 3701-30-09 of the Ohio Administrative Code*

**Issued To:**

██████████ Township Road 319  
Millersburg, OH 44654

Via Certified Mail

**For the property located at:** ██████ N Washington St, Millersburg, OH 44654 ██████

On August 21, 2019, lead-based paint testing was performed at ██████ N Washington St, Millersburg, OH 44654-██████ because a ██████ was associated with this property.

**You have 90 days from the receipt of this order to repair the following hazards. The hazards MUST be repaired by an Ohio licensed lead abatement contractor. You are REQUIRED to deliver a copy of this order to the occupants of each unit under this order.**

**Lead paint hazards:**

**Outside of the house:**

Exterior, basement window casing on side(s) B, D, All, basement floor  
Exterior, basement window jamb on side(s) B, D, All, basement floor  
Exterior, basement window sash on side(s) B, D, All, basement floor  
Exterior, basement window sill on side(s) B, D, All, basement floor  
Exterior, window apron on side(s) A, B, All; C1, 1st floor  
Exterior, window casing on side(s) A, B, All; C1, 1st floor  
Exterior, window jamb on side(s) A, B, All; C1, 1st floor  
Exterior, window sash on side(s) A, B, All; C1, 1st floor  
Exterior, window sill on side(s) A, B, All; C1, 1st floor  
Exterior, window stop on side(s) A, B, All; C1, 1st floor  
Exterior, window trough on side(s) A, B, All; C1, 1st floor  
Front porch, box beam on side(s) A, B, D, 1st floor

Front porch, ceiling 1st floor  
Front porch, door on side(s) C, 1st floor  
Front porch, door casing on side(s) C, 1st floor  
Front porch, door jamb on side(s) C, 1st floor  
Front porch, door stop on side(s) C, 1st floor  
Front porch, door threshold on side(s) C, 1st floor  
Front porch, wall on side(s) B, C, D, 1st floor  
Back porch, box beam on side(s) C, 1st floor  
Back porch, ceiling 1st floor  
Back porch, column on side(s) B, C, 1st floor  
Back porch, door on side(s) A, 1st floor  
Back porch, door casing on side(s) A, 1st floor  
Back porch, door jamb on side(s) A, 1st floor  
Back porch, door stop on side(s) A, 1st floor  
Back porch, floor  
Back porch, half wall on side(s) C, 1st floor  
Back porch, door threshold on side(s) A, 1st floor

**Inside of the house:**

Bathroom 1, door jamb on wall B  
Bathroom 1, door stop on wall B  
Dining room, baseboard on wall(s) A, B, C, D  
Dining room, entry casing on wall C  
Dining room, entry jamb on wall C  
Dining room, window sill on wall(s) B, left, right  
Family room, baseboard on wall(s) A, B, C, D  
Family room, window sill on wall(s) A, left, right  
Storage room, door casing on wall A  
Storage room, door jamb on wall A  
Storage room, door stop on wall A  
Stairwell 1, door on wall D  
Stairwell 1, door casing on wall D  
Stairwell 1, door jamb on wall D  
Stairwell 1, door stop on wall D  
Stairwell 1, door threshold on wall D  
Stairwell 1, wall A, B, C, D

**Lead soil hazards:**


Side C, drip line  
Side C, yard


Once the lead hazards are fixed by a licensed lead abatement contractor, a final inspection (also known as a "clearance examination") is required. The final inspection MUST be done by an Ohio licensed lead risk assessor.

This lead hazard control order will not be lifted until the Ohio Department of Health receives and approves the clearance examination report. The report should be faxed to Andrew Schumacher at 614-728-6793 or emailed to [andrew.schumacher@odh.ohio.gov](mailto:andrew.schumacher@odh.ohio.gov). Once the report is approved, a *Notice of Compliance* letter will be mailed to you.

**\*\*\*\*If you do not comply with this lead hazard control order, the Ohio Department of Health may issue an Order to Vacate which would prohibit anyone from living in the residence or using it as a child day-care or school. A warning sign would be posted to show the public that the property is unsafe.\*\*\*\***

Should you have any questions about this order, please call Andrew Schumacher at 614-752-9588.

  
\_\_\_\_\_  
Amy Acton, M.D., MPH  
Director

  
\_\_\_\_\_  
Date

Enclosures

cc: File